

EAST - [golf cart:2]

File View Edit Tools Window Help

Drafts

- IS&R:
- BRS:
- BRS: bumper with bracket with
- BRS:
- BRS:
- BRS: bipart\$
- BRS: 11 and
- BRS: 17 and

Pending

Active

- L1: (666) (296/204,203.04).CCLS.
- L2: (130) 11 and (cut or notch)
- L3: (76) 11 and (cut or notch) and (bracket or suspension)
- L4: (248) 11 and "280"/\$.ccls.
- L5: (61) 14 and side near2 member
- L6: (0) suspension near2 mount with side near2 member with
- L7: (0) suspension near2 mount with side near2 member with
- L8: (0) suspension near2 mount with side near2 member with
- L9: (15) suspension near2 mount with side near2 member

Failed

- ("296/214.ccls.-296/224.ccls.").CCLS.
- ("296/\$.ccls.").CCLS.
- ("296/\$.ccls.").CCLS.
- "11" and (stop adj2 block)
- M.E.D.
- ("200/\$.ccls.").CCLS.
- "/"100/c ccls "" ccls

Search List Browse Queue Clear

DBs US-PGPUB Plurals

Default operator: OR  Highlight all hit terms initially

suspension near2 mount with  
side near2 member

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (7)

UDC

Queue

Trash

	U	I	Document ID	Issue Dat	Page	Title	Current C
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6648401	20031118	10	Motor vehicle body with wheelhouse/underbody_re	296/198
			B2				
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6434907	20020820	15	Closed channel structural_member_havin	52/731.6
			B1				
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6270152	20010807	12	Vehicle body structure	296/203.0
			B1				
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5567005	19961022	13	Car body work sub-frame mounting_structure	296/204
			A				
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5549350	19960827	21	Rear underbody structure	296/204
			A				
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5468018	19951121	7	Torque box assembly for a vehicle	280/788
			A				
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 4708391	19871124	6	Rear body structure for motor_vehicle	296/204
			A				

Hits Details HTML

Ready

NUM

ST AVAILABLE COPY

**EAST - [golf cart:2]**

File View Edit Tools Window Help

Drafts

- IS&R:
- BRS:
- BRS: bumper with bracket with
- BRS:
- BRS:
- BRS: bipart\$
- BRS: 11 and
- BRS: 17 and

Pending

Active

- L1: (666) (296/204,203.04).CCLS.
- L2: (130) 11 and (cut or notch)
- L3: (76) 11 and (cut or notch) and (bracket or suspension)
- L4: (248) 11 and "280"/\$.ccls.
- L5: (61) 14 and side near2 member
- L6: (0) suspension near2 mount with side near2 member with
- L7: (0) suspension near2 mount with side near2 member with
- L8: (0) suspension near2 mount with side near2 member with
- L9: (15) suspension near2 mount with side near2 member

Failed

- ("296/214.ccls.-296/224.ccls.").CCLS.
- ("296/\$.ccls.").CCLS.
- ("296/\$.ccls.").CCLS.
- "11" and (stop adj2 block)
- M.E.D.
- ("200/\$.ccls.").CCLS.
- "/"100/c ccls "" ccls

Custom form BRS form IS&R form Hits

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (7)

UDC

Queue

Trash

	Type	L #	Hits	Search Text	DBs	Time Stam	Comment	Error
1	IS&R	L1	666	(296/204,203.04).CCLS	US-P GPUB	2005/01/1 1 08:47		
2	BRS	L2	130	11.and (cut or notch)	US-P GPUB	2005/01/1 1 08:47		
3	BRS	L3	76	11 and (cut or notch) and (bracket or suspe	US-P GPUB	2005/01/1 1 08:49		
4	BRS	L4	248	11 and "280"/\$.ccls.	US-P GPUB	2005/01/1 1 08:50		
5	BRS	L5	61	14 and side near2 member	US-P GPUB	2005/01/1 1 08:52		
6	BRS	L6	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
7	BRS	L7	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
8	BRS	L8	0	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		
9	BRS	L9	15	suspension near2 mount with side near2	US-P GPUB	2005/01/1 1 08:53		

Hits Details HTML

Ready

AVAILABLE COPY